



Dimensioni (mm) Dimensions (mm)		
$d_{(F7)}$	$D_{(m6)}$	L ^{-0,10 -0,30}
8	12	8
		10
		12
		15
10	14	8
		10
		12
		15
		20
		12
10		
12		
15		
16		
19		
20		
25		
13	19	10
		12
		15
		16
		20
14	20	10
		12
		15
		20
		25
		30
15	21	10
		12
		15
		16
		20
		25
		30
16	22	10
		12
		15
		16
		19
		20
		25
		30
35		
40		
17	23	15
18	24	12

Dimensioni (mm) Dimensions (mm)		
$d_{(F7)}$	$D_{(m6)}$	L ^{-0,10 -0,30}
18	24	15
		16
		20
		25
		30
19	26	15
		20
20	28	10
		12
		15
		16
		19
		20
		25
		30
		40
		45
20	30	16
		20
		25
		30
		35
22	32	12
		15
		20
		25
		30
25	30	16
		20
		25
		30
		35
		40
		45
		50
25	33	12
		15
		16
		20
		25
		30
		35
		40
		45
		50
60		
25	35	12

Dimensioni (mm) Dimensions (mm)		
$d_{(F7)}$	$D_{(m6)}$	L ^{-0,10 -0,30}
25	35	15
		16
		20
		25
		30
		35
28	38	40
		45
		50
		20
		25
30	35	30
		40
		45
		50
		16
		20
		25
		30
30	36	35
		40
		45
		50
		60
		12
30	38	15
		20
		25
		30
		35
		40
		45
		50
30	40	12
		15
		20
		25
		30
		35
		40
		45
		45
		50